



S-TYPE

DATE 02/02
Amended 02/02

S501-S142

SERVICE

TECHNICAL BULLETIN

**Rear Door Glass Inoperative in Hot Climates –
Detached Regulator Mounting – Replace
Regulators – Service Action S142**

MODEL 2000-01 MY
S-TYPE
VIN L00600-M11674

Remove and destroy Bulletin S501-S142, dated 02/02.
Replace with this Bulletin.
Revisions are marked with a bar and in **bold text**.

Issue:

On some 2000-01 MY S-TYPE vehicles (within the above VIN range) that are consistently left outside in high temperatures (e.g. above 25° C) for extended periods of time, the rear door glass regulator may become detached from its mounting, thus preventing the door glass from opening/closing.

Affected Areas/States in North America:

Alabama	Arizona	California	Colorado
Florida	Georgia	Kansas	Louisiana
Nevada	North Carolina	Oklahoma	Puerto Rico
South Carolina	Tennessee	Texas	Utah

Action:

In only those states affected (see table above), all rear door glass regulators should be replaced on S-TYPE vehicles within the above VIN range at the next service opportunity.

To replace the rear door glass regulators, follow the procedure below:

REPAIR PROCEDURE

This workshop procedure is applicable to either the left-hand or right-hand side of the vehicle and should be repeated on the opposite side:

1. Open luggage compartment lid.
2. Displace luggage compartment carpet.
3. Disconnect vehicle battery. (See Workshop Manual, JTIS CD ROM section 414-01, SRO 86.15.01).

▲ Warning: After the battery has been disconnected, wait for one minute for the air bag system to disarm.

4. Remove rear door trim pad for access.



5. Remove rear door quarter light glass. (See Workshop Manual, JTIS CD ROM section 501-11).
6. Remove rear door glass. (See Workshop Manual, JTIS CD ROM section 501-11.)
7. Remove door glass regulator bolts. (See Workshop Manual, JTIS CD ROM section 501-11.)
8. Detach door glass regulator.
9. Disconnect rear door glass regulator electrical connector.
10. Remove door glass regulator.
11. Connect new door glass regulator electrical connector.
12. Align door glass regulator.
13. Install and tighten door glass regulator bolts.
14. Install rear door glass. (See Workshop Manual, JTIS CD ROM section 501-11.)
15. Install rear door quarter light glass. (See Workshop Manual, JTIS CD ROM section 501-11.)
16. Install rear door trim pad.
17. Reconnect vehicle battery. (See Workshop Manual, JTIS CD ROM section 414-01, SRO 86.15.01).
18. Reposition luggage compartment carpet.
19. Close luggage compartment.

Parts Information:

<u>DESCRIPTION</u>	<u>PART NUMBER</u>	<u>QTY</u>
Right hand rear door glass regulator	XR8 32338	1
Left hand rear door glass regulator	XR8 32339	1

Warranty Information:

Service Action S142

CURRENT SYSTEM

<u>VEHICLE</u>	<u>SUMMARY CODE</u>	<u>R.O. NUMBER</u>	<u>DESCRIPTION</u>	<u>TIME ALLOWANCE</u>
S-TYPE 2000-01 MY VIN L00600-M11674	7B	86.25.60	Replace both rear door regulators -without drive-in/out time (performed with another repair.)	2.0 hrs.
S-TYPE 2000-01 MY VIN L00600-M11674	7C	86.25.60 10.10.10	Replace both rear door regulators -with drive-in/out time (only repair performed)	2.0 hrs. 0.1 hrs.

GLOBAL ACES

Some changes to the DDW claim submission system are to be introduced in the near future which will change the entry of some Service Action and Recall Action data. Upon the introduction of the revised DDW claim submission system, the following warranty information will apply.

Warranty claims should be submitted quoting the information found in the table below. This will result in payment of the stated time and where applicable parts/miscellaneous expense codes as listed.

Drive in/Drive out may only be claimed when the vehicle has been brought in for this action to be undertaken alone.

The SROs and parts listed above have been included for information only and there will be no requirement to enter the parts or SROs onto the claim.

Program Code	Option	Description	SRO	Time	Description	Part Number	Qty
S142	B	Replace both rear door regulators	86 25 60	2.0	RH Rear door glass regulator	XR8 32338	1
					LH Rear door glass regulator	XR8 32339	1
S142	C	Replace both rear door regulators	86 25 60	2.0	RH Rear door glass regulator	XR8 32338	1
					LH Rear door glass regulator	XR8 32339	1
		Drive in/Drive out	10 10 10	0.1			

NOTE: Always perform a DCS claim search first to determine whether this service action has been performed on this vehicle. The warranty selection under the vehicle inquiry will give a listing of all claims against the vehicle. If S142 appears in the fault code field, do not perform this service action.

DCS DEALERS

Submit claims using the appropriate summary code for the vehicle model and work performed. Follow standard campaign submission procedures.

NON-DCS DEALERS

Submit claims on the Recall Campaign Summary form W-25. Enter the appropriate summary code for the vehicle model and work performed in the Repair Code column. Do not use the W-1 warranty claim form.