



Sedan Range

DATE 4/95

13-19

SERVICE

TECHNICAL BULLETIN

Discolored Leather Trim – Oatmeal or
Cream – Service Action S609

MODEL 1995 MY
Sedan Range
VIN 724754-728294

ISSUE:

Oatmeal (AGD) or Cream (NDR) trim in 1995 MY Sedan Range vehicles from VIN 724754 to 728294 shows sign of yellowing or discoloration. The discoloration is the result of high temperature or humidity.

ACTION:

Inspect the Oatmeal or Cream colored trim leather of all 1995 MY Sedan Range vehicles within the VIN range at the next service opportunity.

If the leather is “yellowed” when compared to adjacent panels, perform the following actions.

1. Fax a completed Product Quality Report S-94 to Dealer Technical Support at 201-818-9763.
2. Replace the discolored leather trim with the appropriate component.

PARTS INFORMATION:

Refer to the microfiche for parts information.

NOTE: All parts involved in this service action will have a suffix of AGD (oatmeal) or NDR (cream).

WARRANTY INFORMATION:

Service Action S609

Sedan Range 1995 MY VIN 724754 - 728294

<u>MODEL</u>	<u>FAULT CODE</u>	<u>R.O. NUMBER</u>	<u>DESCRIPTION</u>	<u>TIME ALLOWANCE</u>
Vanden Plas XJ12	S609	76.70.61	Rear seat cushion cover L/H - Renew	0.95 hrs.
Vanden Plas XJ12	S609	76.70.60	Rear seat cushion cover R/H - Renew	0.95 hrs.
XJ6, XJR	S609	76.70.47	Rear seat cushion cover, one piece - Renew	1.40 hrs.
All	S609	76.70.48	Rear seat squab cover - Renew	1.85 hrs.
All	S609	76.70.59	Front seat cushion cover - Renew	0.85 hrs.
All	S609	76.70.15	Front seat squab - Renew	1.35 hrs.
All	S609	76.70.14	Front seat headrest, electrically operated - Renew	0.10 hrs.
All	S609	76.70.56	Rear seat headrest - Renew	0.10 hrs.
All	S609	76.34.22	Front door armrest - Renew	0.60 hrs.
All	S609	76.34.23	Rear door armrest - Renew	0.20 hrs.
All	S609	10.10.10	Drive in/out time (Claim only if S609 is the only warrantable repair performed)	0.15 hrs.

CLAIM SUBMISSION PROCEDURE:

Warranty summary codes have not been assigned to this service action due to the number of parts and repair operation combinations.

DCS Dealers

Submit claims using S609 as the fault code with the appropriate information for the vehicle model and work performed. Follow standard claim submission procedures.

Non-DCS Dealers

Submit claims on the W-1 Warranty Claim form using S609 as the Fault Code with the appropriate information for the vehicle model and work performed. Do not use the W-25 Recall Campaign Summary form.