



Sedan Range

DATE 12/94
Amended 6/96

15-24

SERVICE

TECHNICAL BULLETIN

Positive Start Cable –
Reroute –
Service Action S629

MODEL 1995 MY
XJR Sedan
VIN 720125-745782

Remove and destroy Bulletin 15-24, Date 12/94.
Replace with this Bulletin.
Revisions are marked with a bar and indicated in Bold Text.

ISSUE:

The positive starter cable may be incorrectly routed in 1995 MY XJR Sedan vehicles from VIN 720125 - 745782.

ACTION:

Inspect and if necessary correct the routing of the positive starter cable of XJR Sedan vehicles within the VIN range during PDI or at the next service opportunity.

The CORRECT routing of the positive starter cable is shown in Illustration 1. (Starter cable routed BELOW the automatic transmission dipstick tube.

The INCORRECT routing of the starter cable is shown in Illustration 2. (Starter cable routed ABOVE the automatic transmission dipstick tube)

If the positive starter cable is incorrectly routed, reroute following the procedure described below.

POSITIVE STARTER CABLE REROUTING PROCEDURE:

1. Disconnect the battery negative cable.
2. Remove the positive starter cable from the right side firewall stud.
3. Reroute the starter cable from above the automatic transmission dip stick tube (Illustration 2) to below the automatic transmission dipstick tube (Illustration 1).




ILLUSTRATION 1

ILLUSTRATION 2

4. Reconnect the starter cable to the firewall stud and reposition the rubber boot.
5. Reconnect the battery and the clock.

WARRANTY INFORMATION:

Service Action S629

<u>VEHICLE</u>	<u>SUMMARY CODE</u>	<u>DESCRIPTION</u>	<u>TIME ALLOWANC E</u>
XJR Sedan 1995 MY VIN 720125 - 745782	FP	Reroute positive starter cable - no drive in/out time (In conjunction with PDI or other repair)	0.10 hrs.
	FU	Reroute positive starter cable with drive in/out time (Only repair performed)	0.25

NOTE: Due to the minimal time required to inspect the positive starter cable routing, no claim should be submitted when repair is not necessary

CLAIM SUBMISSION PROCEDURE:

Warranty summary codes have been assigned to this service action in order to simplify claim submission. The dealership will be reimbursed the labor time allowance as indicated.

DCS Dealers

Submit claims using the appropriate summary code for the vehicle model and work performed. Follow standard campaign submission procedures.

Non-DCS Dealers

Submit claims on the Recall Campaign Summary form W-25. Enter the appropriate summary code for the vehicle model and work performed in the Repair Code column. Do not use the W-1 warranty claim form.