



XJ range

DATE 05/04

XJ100-02

SERVICE

TECHNICAL BULLETIN

Drive Belt Noise After Cold Start –
Supercharger –
Revised Drive Belt Available

MODEL 2004 MY
XJR
VIN G00421-G33625

Issue:

On some 2004 MY XJ range vehicles, customers may have a concern with noise from the supercharger drive belt after a cold start.

A revised drive belt has been released to address this concern.

Action:

Should a customer express concern of a noise from the supercharger drive belt from cold start, remove the supercharger drive belt to confirm that the noise stops.

If so, install a new modified supercharger drive belt, referring to Workshop Manual, section: 303-05, SRO 18.50.08).

Global Technical Reference (GTR):

Dealer Access: <https://hub.franchise.jaguar.com>

Internet access: <http://www.jaguartechno.com>

Parts Information:

<u>DESCRIPTION</u>	<u>PART NUMBER</u>	<u>QTY</u>
Supercharger drive belt	C2C 26235	1

Warranty Information:

Warranty claims should be submitted quoting the information found in the table below. This will result in payment of the stated time and, where applicable parts/miscellaneous expense codes as listed.

Description	SRO	Time	Causal Part Number
Install a new supercharger drive belt	18.50.08	0.6 hrs.	C2C 26235

NOTE: THE INFORMATION IN TECHNICAL BULLETINS IS INTENDED FOR USE BY TRAINED, PROFESSIONAL TECHNICIANS WITH THE KNOWLEDGE, TOOLS, AND EQUIPMENT TO DO THE JOB PROPERLY AND SAFELY. IT INFORMS THESE TECHNICIANS OF CONDITIONS THAT MAY OCCUR ON SOME VEHICLES, OR PROVIDES INFORMATION THAT COULD ASSIST IN PROPER VEHICLE SERVICE. THE PROCEDURES SHOULD NOT BE PERFORMED BY "DO-IT-YOURSELFERS." DO NOT ASSUME THAT A CONDITION DESCRIBED AFFECTS YOUR CAR. CONTACT A JAGUAR RETAILER TO DETERMINE WHETHER THE BULLETIN APPLIES TO YOUR VEHICLE.

