



Sedan Range

DATE 4/97  
Amended 11/01

05.1-24

SERVICE

## TECHNICAL BULLETIN

MIL Illumination – DTC P0441 –  
Service Action S675

MODEL 1995 MY  
Sedan (4.0L) NA  
VIN 720001-754303

Remove and destroy Bulletin 05.1-24, dated 4/97.  
Replace with this Bulletin.  
Revised text is marked with a bar and in **bold text**.

### ISSUE:

Some 1995 MY Sedan Range vehicles within the above VIN ranges may experience illumination of the Malfunction Indicator Lamp (MIL) caused by DTC P0441 being falsely registered in the Engine Control Module (ECM).

In case of a customer complaint, this condition can be rectified by replacing both of the Programmable Read Only Memories (PROMs) with new PROMs from the appropriate modification kit.

### ACTION:

Refer to **Technical Bulletin 05.1-26, amended 11/01**. The software revisions for **Service Action S675** to solve the above complaint were incorporated in the PROMs designed for Recall R493.