



Sedan Range

DATE 4/98

05.1-32

SERVICE

TECHNICAL BULLETIN

Recall R691 –
Incorrect Emission Control Label –
Install Revised Label – U.S. Vehicles

MODEL 1995 MY XJR
VIN 720001-754303

THIS RECALL ACTION APPLIES TO U.S. VEHICLES ONLY. REFER TO TECHNICAL BULLETIN 05.1-33 FOR CANADIAN VEHICLES.

ISSUE:

On all 1995 Model Year XJR Sedan Models within the above VIN range, the factory-installed Emission Control Data Label ("Tune-up Label") was incorrectly specified. This label is applied to the crossmember above the radiator, within the engine compartment. 1995 MY XJ6 4.0L Sedan models with naturally-aspirated AJ16 engines are NOT affected.


The existing label implies that the engine is equipped with an Exhaust Gas Recirculation system which is not the case.

Jaguar Cars will contact customers by mail. The necessary replacement labels for this purpose, bearing the correct wording, will be supplied to you by Jaguar Cars.

ACTION:

On all 1995 MY XJR vehicles, proceed as follows:

- 1. Check the driver's door B-pillar area for an R691 authorized modification label used both in Canada and the U.S.A. (Illustration 1). If no label is found, continue with step 2.



ILLUSRATION 1



LOCATION OF EMISSION CONTROL DATA LABEL




ILLUSTRATION 2

2. Identify the Emission Control Data Label (“Tune-up Label”), located on the left side of the cross panel above the radiator (Illustration 2).
3. Clean off the existing label.
4. Apply the replacement label over the old label.
5. Apply an R691 authorized modification label to the Driver side B-pillar. (This label will immediately indicate to any other Dealer that the vehicle concerned has already been rectified).

PARTS INFORMATION:

One Vehicle Emission Control Information Label will be supplied to you direct, on a free-of-charge basis. After determining their immediate needs, dealers should order additional labels by contacting the Jaguar Cars Product Legislation & Compliance Dept. at 201-818-8202 or 8025.

WARRANTY INFORMATION:

NOTE: Always perform a DCS claim search first to determine whether this recall has been performed on this vehicle. The warranty selection under the vehicle inquiry will give a listing of all claims against the vehicle. If R691 appears in the fault code field, do not perform this recall.

Recall Action R691

<u>VEHICLE</u>	<u>SUMMARY CODE</u>	<u>DESCRIPTION</u>	<u>TIME ALLOWANCE</u>
(Non-California registered vehicles):			
XJR (4.0L) 1995 MY VIN 720001-754303 Model code 2314	AJ	Install revised emissions label -without drive-in/out time (performed with another repair)	0.10 hrs.
XJR (4.0L) 1995 MY VIN 720001-754303 Model code 2314	AK	Install revised emissions label -with drive-in/out time (only repair)	0.25 hrs.

(California dealers and California registered vehicles):

XJR (4.0L) 1995 MY VIN 720001-754303 Model code 2314	AL	Install revised emissions label -without drive-in/out time (performed with another repair)	0.10 hrs.
XJR (4.0L) 1995 MY VIN 720001-754303 Model code 2314	AM	Install revised emissions label -with drive-in/out time (only repair)	0.25 hrs.

Note: California dealerships must claim either summary code 'AL' or 'AM' regardless of vehicle's state of registration. Non-California dealerships should claim either summary code 'AL' or 'AM' only when the vehicle in question is registered in the state of California. On all other vehicles (registered outside the state of California) non-California dealerships should use either summary code 'AJ' or 'AK'.

Note: This Recall applies to U.S. vehicles only. In the event of a Canadian vehicle requiring this action in the U.S., refer to Technical Bulletin 05.1-33, "Incorrect Emission Control Data Label in Engine Compartment - Service Action S691." This same repair is a Service Action in Canada. The same modification label is used for vehicles in both the U.S.A. and Canada.