

TECHNICAL BULLETIN

	<p>MIL Illumination – DTC P0300 – Service Action S659</p> <p>MODEL 4.0L Normally Aspirated 1996 MY DATE 11/95 XJS VIN 222632 - 224124</p>	<p>18-49 Amended 2/98</p>
-----------------------------------------------------------------------------------	-------------------------------------------------------------------------------------------------------------------------------------------------------------	--------------------------------------------------------

Remove and destroy Bulletin 18-49, dated 11/95.
Replace with this Bulletin.
Revised text is marked with a bar and in **bold text**.

ISSUE:

Some 1996 MY vehicles within the above VIN range may experience illumination of the Malfunction Indicator Lamp (MIL) caused by DTC P0300 being set. The DTC is set due to close software tolerances in the ECM rather than a mechanical problem with the engine.

This condition can be rectified by replacing one or both of the Programmable Read Only Memories (PROMs), depending on the VIN, with new PROM(s) from the appropriate modification kit.

ACTION:

Refer to **Technical Bulletin 18-52, dated 4/97**. The **software revisions for Service Action S659** to solve the above complaint were incorporated in the PROMs designed for **Service Action S676**.