

TECHNICAL BULLETIN

	<p>Momentary Engine Hesitation/ Instability – Service Action S676</p> <p>MODEL XJS (4.0L) 1996 MY VIN 222632-226644</p> <p>DATE 4/97</p>	<p>18-52 Amended 11/01</p>
---	---	---

Remove and destroy Bulletin 18-52, dated 4/97.
Replace with this Bulletin.
Revised text is marked with a bar and in **bold text**.

ISSUE:

Some 1996 MY XJS vehicles within the above VIN ranges may experience a momentary engine hesitation/instability while cruising at steady highway speeds. This condition may be accompanied by a very brief illumination of the "Check Engine" Malfunction Indicator Lamp (MIL).

This condition can be rectified by replacing both of the Programmable Read Only Memories (PROMs) with new PROMs from the appropriate modification kit.

In addition, this Service Action supersedes S659 (Bulletin 18-49) and S 672 (Bulletin 18-51)

ACTION:

Refer to **Technical Bulletin 17-12, amended 11/01**. The software revisions for **Service Action S676** to solve the above complaint were incorporated in the PROMs designed for Recall R493.