



Sedan Range

DATE 4/97
Amended 11/01

05.1-25

SERVICE

TECHNICAL BULLETIN

Momentary Engine Hesitation/Instability – Service Action S676

MODEL 1996-97 MY
Sedan (4.0L) Range
VIN 754304-802987

Remove and destroy Bulletin 05.1-25, dated 4/97.
Replace with this Bulletin.
Revised text is marked with a bar and in **bold text**.

ISSUE:

Some 1996-97 MY Sedan Range vehicles within the above VIN ranges may experience a momentary engine hesitation/instability while cruising at steady highway speeds. This condition may be accompanied by a very brief illumination of the "Check Engine" Malfunction Indicator Lamp (MIL).

This condition can be rectified by replacing both of the Programmable Read Only Memories (PROMs) with new PROMs from the appropriate modification kit.

ACTION:

Refer to **Technical Bulletin 05.1-26, amended 11/01**. The software revisions for **Service Action S676** to solve the above complaint were incorporated in the PROMs designed for Recall R493.