



Sedan Range

DATE 6/95

15-28

SERVICE

TECHNICAL BULLETIN

Electrical Connectors – Contamination

MODEL 1995 MY-ON
Sedan Range

VIN
720001-ON

ISSUE:

Silicone-based lubricants or high pressure steam cleaning can penetrate and contaminate electrical connections causing increased electrical resistance. Silicone lubricants will seep into the connectors via capillary action; pressure cleaning will force moisture and other contaminants into the connector.

ACTION:

Do not use silicone lubricants or steam pressure cleaning equipment on or near electrical connectors.