



V8 XJ Series/XK8

DATE 9/98

303-29

SERVICE

TECHNICAL BULLETIN

Idle Quality – Spark Plugs – Revised Gaps

MODEL

1997 MY-ON XK8 Range
1998 MY-ON V8 XJ Series

VIN

001001-ON
812256-ON

Issue:

The specification for spark plug gaps on all V8 engines has been revised to improve engine idling quality.

Action:

When installing a set of spark plugs check, and if necessary, reset the gaps to 1.3 mm (0.052 inch) before installation.

This policy applies only when a set of spark plugs is replaced at a routine service interval, or as the result of a customer complaint. Do **not** remove or replace existing spark plugs just to increase the gap.

SERVICE INTERVAL - V8 ENGINES

Normally aspirated	100,000 miles
Supercharged	60,000 miles

Warranty Information:

This Technical Bulletin is issued for information only.