



Sedan Range

DATE 2/98

05.1-30

SERVICE

TECHNICAL BULLETIN

Replacement Air Injection Pump – Upgrade Fuse Rating

MODEL 1995-97 MY
Sedan (4.0L) Range
VIN 720001-812255

ISSUE:

Once the supply of the current air pumps (part no. LHE 1545AC) is exhausted, an alternative pump (part no. LHE 1545AD) will be supplied. The alternative pump is interchangeable with the other pump, but requires a fuse upgrade from 25 to 30Amps.

ACTION:

When installing an air injection pump LHE 1545AD as a replacement for any earlier pump, replace Fuse 7 in the RH engine bay fuse box with a 30Amp fuse (color: light green, part no. LST 8731AA).

Refer to page 26 of the Sedan Electrical Guide for the specific model year, for further information.