



X-TYPE

DATE 05/02  
Amended 03/03

XT419-S920

SERVICE

# TECHNICAL BULLETIN

General Electronic Control Module (GECM) –  
Replace –  
Service Action S 920

MODEL 2002 MY  
X-TYPE  
VIN C00344-C25928

Remove and destroy Bulletin XT419-S920 dated 05/02.  
Replace with this Bulletin.  
**This Service Action is superseded by Recall R935.**

**Issue:**

The General Electronic Control Module (GECM) installed in some X-TYPE vehicles (within the above VIN range) may experience an internal circuit failure. This condition could lead to intermittent operation of some electrical systems.

**Action:**

Refer to Recall R935 described in Technical Bulletin **XT413-R935** dated 03/03.