



MODEL
2007 XK

DATE
06 June 2006

NUMBER
XK100-001

SERVICE

TECHNICAL BULLETIN

SECTION: 100-00

New PDI Instructions to Activate Passive System

AFFECTED VEHICLE RANGE:

New XK

VIN: B05215 onwards

Model Year: 2007 onwards

CONDITION SUMMARY:

ACTIVATE PASSIVE SYSTEM WITH NEW IDS PDI APPLICATION



NOTE: Edition 4 of the Pre-Delivery Instruction (PDI) Manual posted on GTR reflects enhancements made to the Integrated Diagnostic System (IDS) DVD 101 software. The software enhancements apply to all New XK models and provide new IDS functionality to activate Passive keys for vehicles beginning with VIN B05215. Edition 4 PDI Manual instructions may also be safely used on vehicles before VIN B05215.

Situation: This 'information only' bulletin has been issued to inform dealers that the Passive system has been deactivated during transport on VIN B05215 and later vehicles. Vehicles in this VIN range will only start with the smart key correctly inserted into the docking station, until the Battery Isolation Transit Relay is removed and the PDI procedures are performed.

The Passive system must be activated after the Transit Relay has been removed by completing the IDS PDI application. Vehicles with VIN B05215 and later will only start using the Passive system after the IDS PDI application has been completed.

Action: Refer to Edition 4 (or later) of the PDI Manual instructions on GTR to complete PDI using the IDS DVD 101 (or later) software. Activate the Passive system for VIN B05215 and later vehicles.

TOOLS

IDS DVD101 or later software

WARRANTY:

Information purposes only. Normal warranty policy and procedures apply.

NOTE: The information in Technical Bulletins is intended for use by trained, professional technicians with the knowledge, tools, and equipment required to do the job properly and safely. It informs these technicians of conditions that may occur on some vehicles, or provides information that could assist in proper vehicle service. The procedures should not be performed by "do-it-yourselfers." If you are not a Retailer, do not assume that a condition described affects your vehicle. Contact an authorized Jaguar service facility to determine whether the bulletin applies to a specific vehicle.