

# TECHNICAL BULLETIN



## Brake Pedal Switch – Parts Inventory Simplified

MODEL 1993-94 MY Sedan  
1995-96 MY XJS

DATE 4/98

**70-28**  
Amended  
**11/98**

Remove and destroy Bulletin 70-28, dated 4/98.  
Replace with this Bulletin.  
Revisions are marked with a bar and in **bold text**.

### ISSUE:

The brake pedal switch assembly used on 1998 MY vehicles is now the only switch available for the above vehicles (Illustration 1).

### ACTION:

The current brake pedal switch assembly, as listed on the next page, must be installed if replacement of the switch is necessary. An adapter harness, also listed on the next page, is required to connect the switch to the harness of the above Sedan vehicles. Any excess harness length should be coiled and taped securely in place.




ILLUSTRATION 1

**PARTS INFORMATION:**

<u>DESCRIPTION</u>	<u>PART NUMBER</u>	<u>QTY</u>
Brake pedal switch 1995-96 MY XJS VIN 198335-226645	LJB 6420BA	1
<b>Brake pedal switch 1993-94 MY Sedan</b>	<b>LNB 6420BB</b>	<b>1</b>
Link harness assembly 1993-94 MY Sedan	LNB 3022AA	1

**WARRANTY INFORMATION:**

<u>FAULT CODE</u>	<u>R.O. NUMBER</u>	<u>DESCRIPTION</u>	<u>TIME ALLOWANCE</u>
QN FB 28	86.65.51	Replace brake light switch	0.25 hrs.
	86.99.97	Connect PDU/download capture/printout	0.15 hrs
	<b>86.99.99</b>	<b>PDU test time</b>	<b>0.30 hrs.</b>