

TECHNICAL BULLETIN



CELLULAR TELEPHONE – TRANSCIVER MULTIPLUG – RELOCATED

MODEL **Sedan Range 1994 MY**

DATE **2/95**

86-144
AMENDED
3/95

VIN 695867 -719999

Remove and destroy Bulletin 86-144 , Date 2/95.
Replace with this Bulletin.
Revisions are marked with a bar and indicated in Bold Text.

ISSUE:

The cellular telephone transceiver multiplug in 1994 MY Sedan Range vehicles was relocated in production to improve service accessibility. The multiplug is now behind the fuel tank trim panel adjacent to the battery tray casing in vehicles from VIN 695867 - 719999.

ACTION:

To access the cellular telephone transceiver multiplug, remove the spare tire and fuel tank trim panel.