



Sedan Range

DATE 7/95

12-08

**SERVICE**

**TECHNICAL BULLETIN**

Unsold Stock Vehicles –  
Replace Front Brake Pads –  
Service Action S 646

MODEL 1995 MY  
Sedan Range  
VIN  
720001-739080

**ISSUE:**

The front brake pad material on vehicles in the above VIN ranges may leave deposits on the brake discs causing brake pulsation.

**ACTION:**

Replace the front brake pads of all unsold 1995 MY Sedan Range vehicles within the above VIN ranges.

**NOTE:** This Service Action applies to new in-stock vehicles that are not being used as demonstrators, are not in use, and have not been sold to retail customers.

**PARTS INFORMATION:**

**DESCRIPTION**

Front Brake Pad kit

**PART NUMBER**

JLM 1829

**QTY**

1



**WARRANTY INFORMATION:**

**Service Action S646**

<b><u>VEHICLE</u></b>	<b><u>SUMMARY CODE</u></b>	<b><u>DESCRIPTION</u></b>	<b><u>TIME ALLOWANCE</u></b>
Sedan Range 1995 MY VIN 720001-739080 Model codes 2310, 2311, 2313, 2314, 2512 IN-STOCK VEHICLES ONLY	HT	Front Brake Pads - Replace	0.65 hrs.
Sedan Range 1995 MY VIN 720001-739080 Model codes 2310, 2311, 2313, 2314, 2512 IN-STOCK VEHICLES ONLY	HU	Front Brake Pads - Replace with drive in/out time	0.80 hrs.

**CLAIM SUBMISSION PROCEDURE:**

Warranty summary codes have been assigned to this service action in order to simplify claim submission. The dealership will be reimbursed the parts and labor time allowance as indicated.

**DCS DEALERS**

Submit claims using the appropriate summary code for the vehicle model and work performed. Follow standard campaign submission procedures.

**NON-DCS DEALERS**

Submit claims on the Recall Campaign Summary form W-25. Enter the appropriate summary code for the vehicle model and work performed in the Repair Code column. Do not use the W-1 warranty claim form.