



Sedan Range

DATE 4/98
Amended 11/98

12-10

SERVICE

TECHNICAL BULLETIN

Brake Pedal Switch – Parts Inventory Simplified

MODEL 1995-97 MY
Sedan Range
VIN 720001-812255

Remove and destroy Bulletin 12-10, dated 4/98.
Replace with this Bulletin.
Revisions are marked with a bar and in **bold text**.

ISSUE:

The brake pedal switch assembly used on 1998 MY Sedans is now the only switch available for 1995-97 MY Sedans (Illustration 1).

ACTION:

The current brake pedal switch assembly, as listed on the next page, must be installed if replacement of the switch is necessary. An adapter harness, also listed on the next page, is required to connect the switch to the harness of the 1995-96 MY vehicles (VIN 720001-787953). Any excess harness length should be coiled and taped securely in place. The switch connects directly to the existing vehicle harness on 1997 MY vehicles (VIN 787954-812255).

BRAKE PEDAL SWITCH




ILLUSTRATION 1

PARTS INFORMATION:

<u>DESCRIPTION</u>	<u>PART NUMBER</u>	<u>QTY</u>
Brake pedal switch	LNB 6420BB	1
Link harness assembly (VIN 720001-787953)	LNB 3022AA	1

WARRANTY INFORMATION:

<u>FAULT CODE</u>	<u>R.O. NUMBER</u>	<u>DESCRIPTION</u>	<u>TIME ALLOWANCE</u>
QN FB LF	86.65.51	Replace brake light switch	0.20 hrs.
	86.99.97	Connect PDU/download capture/printout	0.15 hrs
	86.99.99	PDU test time	0.30 hrs.