



Sedan Range

DATE 6/96

15-19

SERVICE

TECHNICAL BULLETIN

Revised Windshield Wiper Blade –
Washer Fluid Mix – Maintenance

MODEL 1996 MY-ON
Sedan Range

VIN

754304-ON

ISSUE:

A new windshield wiper blade design was introduced at the above VIN, to counteract any tendency for the windshield wiper blade to vibrate during operation.

The specification of the windshield washer solution remains a ratio of one part of water to one part washer fluid for the U.S.A and Canada.

ACTION:

When refilling washer reservoirs, refer to the guidelines displayed on the washer fluid container.

Replace the wiper blade and clean the windshield with Jaguar screen clean paste at the following maintenance intervals:

USA: every 7,500 miles.

Canada: every 12 months/16,000 km.

PARTS INFORMATION:

<u>DESCRIPTION</u>	<u>PART NUMBER</u>	<u>QTY</u>
Wiper blade	GNA 8960AA	1
Screen clean paste	DBC-5676	1