



Sedan Range

DATE 1/96

15-21

SERVICE

TECHNICAL BULLETIN

Seat Memory Functions – Inoperative – Revised Seat Control Module

MODEL 1995 MY
Sedan Range
VIN
720001 - 768224

ISSUE:

On Sedan Range vehicles within the above VIN range, the Seat Control Module (SCM) may become temporarily inoperative. After disconnecting the vehicle battery for 10 seconds and then reconnecting it, the SCM can function again. A revised Seat Control Module (SCM) was introduced from VIN 768225 to resolve this specific malfunction. The revised SCM is marked with the part no. LNA 2165AD. The revised SCM can be installed on earlier vehicles if the malfunction is experienced when performing the diagnostic procedure below.

ACTION:

In case of a complaint of inoperative seat memory functions on a Sedan Range vehicle within the above VIN range, perform the following diagnosis to determine whether the installation of a revised SCM is justified:

1. Note which of the seat functions are inoperative including "Memory Set" and "Memory Recall."
2. Disconnect the vehicle battery for 10 seconds. Reconnect the battery.
3. Recheck the seat functions.
4. If the seat functions now operate correctly, install a revised SCM.
6. If the seat functions are still inoperative or incorrect, proceed through normal fault diagnostics. Refer to the Sedan Range 1995 Electrical Guide Fig. 14.2 (driver seat) or 14.6 (passenger seat).
6. Reset the clock after completing fault diagnostics and repairs.

PARTS INFORMATION:

<u>DESCRIPTION</u>	<u>PART NUMBER</u>	<u>QTY</u>
Seat Control Module	LNA 2165AD	1

WARRANTY INFORMATION:

<u>FAULT CODE</u>	<u>R.O. NUMBER</u>	<u>DESCRIPTION</u>	<u>TIME ALLOWANCE</u>
SX CB KD	86.75.15.09	Replace SCM	0.20 hrs.