



Sedan Range

DATE 12/94  
Amended 9/96

15-23

**SERVICE**

**TECHNICAL BULLETIN**

**Power Seat Fuses – Blow with No System  
Fault – Fuse Rating Revised**

MODEL 1995 MY  
Sedan Range  
VIN 720001-724517

Remove and destroy Bulletin 15-23, Date 12/94.  
Replace with this Bulletin.  
Revisions are marked with a bar and indicated in Bold Text.

ISSUE:

Power seat fuses blow with no electrical or mechanical fault in the system.

The 1995 MY Sedan Range power seat fuse specification was increased to 20 Amperes capacity (yellow) from 15 Amperes capacity (light blue) beginning with VIN 724518

NOTE: The fuse box labels have not been changed

ACTION:

If any of the power seat fuses blow in 1995 MY Sedan Range vehicles from VIN 720001 - 724517 with no apparent fault in the system, replace the four 15 Ampere power seat fuses (light blue) with 20 Ampere fuses (yellow).

The power seat fuses are located in the left and right side heel board fuse boxes in positions F3 and F4.

After ensuring that 20 Ampere fuses are fitted, verify that all seat movement functions operate correctly.

CAUTION: Never install fuses with higher amperage ratings than specified by Jaguar. Excessive amperage will cause damage to vehicle electronic components.  
Upgrade fuse specifications only when instructed by a technical bulletin or electronic mail.