

CD Autochanger – Transit Screws –
Storage Location

MODEL 1995-96 MY
Sedan Range
VIN
720001-ON

ISSUE:

The internal mechanism of CD Autochanger units (part no. LXF 4160CA) is locked during shipping by three transit screws on the bottom of the unit. These screws are removed when the unit is installed in the vehicle, but must be stored in the vehicle for reuse if the unit needs to be shipped.

Starting with VIN 787300, these screws should be placed in the storage holes now provided on the rear face of the unit.

ACTION:

When removing the CD Autochanger for repair or replacement, **reinstall all three** transit screws into the three holes on the bottom of the unit, before the Autochanger is packed for shipping.

NOTE: Correct installation of **all three** transit screws is essential to prevent damage to the mechanism during shipping.

The storage location is shown in Illustration 1.

Pack the CD Autochanger in the box of the replacement changer using all padding and packaging materials.




ILLUSTRATION 1