



Sedan Range

DATE 11/98
Amended 06/00

19.1-01

SERVICE

TECHNICAL BULLETIN

Squeaks & Rattles – Section Contents

MODEL 1995-97 MY
Sedan Range
VIN
720001-812255

Remove and destroy Bulletin 19.1-01, dated 11/96.
Replace with this Bulletin.
The listing of bulletins has been updated.

ISSUE:

Section 19 is subdivided according to the area of the vehicle that is the cause of the concern.

ACTION:

Ensure that bulletins are filed in numerical order regardless of date of issue.

<u>NO.</u>	<u>TITLE</u>	<u>DATE</u>
19	Squeaks & Rattles	
19.1-04	Squeaking Interior Trim - KRYTOX Fluid For Trim Refinement Applications	10/98
19.1-03	Squeaks & Rattles - Anti-Squeak Materials	6/96
19.1-02	Not issued	
19.1-01	Squeaks & Rattles - Section Index	11/98
19.2	Doors/Windows	
	None issued	
19.3	Seats	
	None issued	
19.4	Steering Wheel & Column	
	None issued	

19.5 Instrument Panel & Glove Box

- 19.5-04 Squeaks & Rattles - Noise From Console Veneer & Trim - Install Anti-squeak Tape 10/96
- 19.5-03 Squeaks & Rattles - Noise From Harness & Airbag Frame - Repair Procedure 6/96
- 19.5-02 Squeaks & Rattles - Airbag Door and Fascia Noise - Repair Procedure 6/96
- 19.5-01 Squeaks & Rattles - Airbag Door - Adjusting Clearances 6/96

19.6 Vehicle Exterior

- 19.6-07 Squeaks & Rattles - Noise From Fascia - Movement of Steering Column Upper Bracket 5/97
- 19.6-06 Non-NAS Bulletin 12/96
- 19.6-05 Squeaks & Rattles - Wiper Box & Harness - Install Foam Pad 10/96
- 19.6-04 Squeaks & Rattles - Noise From PAS Reservoir 10/96
- 19.6-03 Squeaks & Rattles - Traction Control Cable - Check Cable Position 6/96
- 19.6-02 Squeaks & Rattles - Noise from Traction Control Actuator - Install Isolating Pads 6/96
- 19.6-01 Squeaks & Rattles - Noise from Bulkhead Brake Line - Install Isolating Pads & Clip 6/96

19.7 Vehicle Chassis

- 19.7-05 Rattle - Rear of Vehicle Underbody - Repair Procedure 3/00
- 19.7-04 Clicking Noise from Front of Vehicle - Brake Disc Dust Shield - Install Revised Dust Shield 10/96
- 19.7-03 Knocking from Front Suspension - Shock Absorber Mounting - Repair Procedure 6/96
- 19.7-02 Front Suspension Knock - Stabilizer Bar Contact - Increase Clearance 5/96
- 19.7-01 Powertrain 4L80-E Transmission - Noisy Rear Mount - Modification Procedure 9/95