



V8 XJ Series/XK8

DATE 06/00

501-42

SERVICE

TECHNICAL BULLETIN

Poor Seat Heating – Install Later Specification Seat Heater Pads – Installation Procedure

MODEL

1997-99 MY XK8 Range
1998-99 MY V8 XJ Series

VIN

001001-042775
812256-878717

Issue:

On a customer complaint basis only, in the event of a concern of poor performance of seat heater pads, it is possible to fit to certain earlier vehicles the seat heater pads as fitted from the commencement of 2000 Model Year production. These later pads extend into the side and front rolls of the seat cushions and provide improved heating.

Action:

In case of a customer complaint, it is not necessary to replace all the heater pads in the vehicle, only modify the seat(s) which is/are the source of the customer complaint. It is, however, necessary to replace both the cushion heater pad and the squab heater pad in any one seat, since the two pads are wired in series and are considered to be a matched pair.

On 2000 MY vehicles, or on earlier vehicles which have been upgraded to the 2000 MY heater pads, the heater pads can be replaced individually in case of a failure of either the cushion heater pad or squab heater pad.

1998-99 MY VDP vehicles already have the larger heater pads that extend into the front and side rolls of the front seats. Only the rear seats of these models are eligible for this modification procedure.

PROCEDURE:

In all cases it is necessary to remove from the seat the cushion and/or squab covers to provide access to the heater pad(s). The redundant pad may then be peeled away from the cover and the replacement heater pad fixed in its place.

XK8 FRONT SEAT, CUSHION COVER

A procedure for removal of the squab cover and heater pad is included in the more extensive procedure contained in Technical Bulletin 501-37.

XK8 FRONT SEAT, SQUAB COVER

Refer to JTIS, Front Seat Squab Cover and Foam Pad - SRO: 76.70.06

V8 XJ SERIES

The following Removal & Installation procedures are available on JTIS:

- Powered Front Seat, Cushion Heater Element - SRO: 86.75.13
- Powered Front Seat Squab Heater - SRO: 86.75.14
- Rear Seat Cushion Cover - SRO: 76.70.47
- Rear Seat Squab Cover - SRO: 76.70.48

Parts Information:

<u>DESCRIPTION</u>	<u>PART NUMBER</u>
XX8 right front cushion heater	LJD 2700AA
XX8 left front cushion heater	LJD 2701AA
XX8 front squab heater	LJD 2706AA
XJR only right front cushion heater	LNF 2700CA
XJR only left front cushion heater	LNF 2701CA
XJR only front squab heater	LNF 2704CA
XJR only right rear cushion heater	LNF 2702CA
XJR only left rear cushion heater	LNF 2703CA
XJR only rear squab heater	LNF 2708CA
XJ8 & VDP right front cushion heater	LNF 2700AA
XJ8 & VDP left front cushion heater	LNF 2701AA
XJ8 & VDP front squab heater	LNF 2704AA
XJ8 & VDP right rear cushion heater	LNF 2702AA
XJ8 & VDP left rear cushion heater	LNF 2703AA
XJ8 & VDP rear squab heater	LNF 2708AA

Warranty Information:

<u>FAULT CODE</u>	<u>R.O. NUMBER</u>	<u>DESCRIPTION</u>	<u>TIME ALLOWANCE</u>
SZ ** 42	86.75.13	Front Seat - Cushion Heater Pad - Renew XK8 V8 XJ Series	1.05 hrs. 1.30 hrs.
SZ ** 42	86.75.14	Front Seat - Squab Heater Pad - Renew XK8 V8 XJ Series	0.65 hrs. 1.45 hrs.
	86.75.14/50	V8 XJ VDP Only	1.60 hrs.
SZ ** 42	86.75.37	Rear Seat - Cushion Heater Pad - One Side - Renew V8 XJ Series	1.55 hrs.
SZ ** 42	86.75.38	Rear Seat - Cushion Heater Pad - Vehicle Set - Renew V8 XJ Series	1.65 hrs.
SZ ** 42	86.75.35	Rear Seat - Squab Heater Pad - One Side -Renew V8 XJ Series	2.05 hrs.
SZ ** 42	86.75.36	Rear Seat - Squab Heater Pad - Vehicle Set - Renew V8 XJ Series	2.15 hrs.

- ** FM Cushion Heater - Driver's Seat
- FN Squab Heater - Driver's Seat
- LM Cushion Heater - Passenger's Seat
- LN Squab Heater - Passenger's Seat
- QB Cushion Heater - Left Rear Seat
- QC Squab Heater - Left Rear Seat
- TB Cushion Heater - Right Rear Seat
- TC Squab Heater - Right Rear Seat