

TECHNICAL BULLETIN



Climate Control System – Revised Pipe and Pressure Switch Location

82-45

MODEL Sedan (4.0) Range 1993-94 MY DATE 8/95
with R-134a systems

ISSUE:

The high-pressure pipe from the condenser to the expansion valve has been superseded to part no. MMD-7360AB plus LMD 3997CA. This pipe separates the single pressure switch from the triple pressure switch to a location at the opposite end of the assembly. The triple pressure switch remains near the expansion valve, while the single pressure switch is relocated to the condenser end of the pipe, Illustration 1.

ACTION:

When installing the later style pipe (MMD-7360AB), obtain the link lead LMD-3997CA to connect the single pressure switch to the vehicle harness.




ILLUSTRATION 1

PARTS INFORMATION:

DESCRIPTION

A/C Pipe
Link lead

PART NUMBER

MMD 7360AB
LMD 3997CA