

Sedan Range

DATE 10/94

13-08

SERVICE

TECHNICAL BULLETIN

Hood Ornament – Transit Screws – Must Be Removed

MODEL 1995-96 MY Sedan Range VIN

720001-ON

ISSUE:

The optional "Leaping Jaguar" hood ornament on 1995 MY Sedan Range vehicles is fitted with two transit screws to prevent damage during shipping. THESE SCREWS MUST BE REMOVED AND DISCARDED BEFORE THE VEHICLE IS PUT INTO SERVICE.

To minimize the risk of personal injury, the Leaping Jaguar is designed to swivel and flex on the base in the event of a heavy impact.

IMPORTANT: LEAPING JAGUAR HOOD ORNAMENT TRANSIT SCREWS MUST BE REMOVED BEFORE THE VEHICLE IS PUT INTO SERVICE

ACTION:

Remove and discard the hood ornament transit screws on all 1995 MY Sedan Range vehicles before the vehicles are put into service.

- Open the hood and remove the two #2 posi-drive transit screws located immediately to the front and rear of the nylon hood ornament retaining nut.
- Do not remove the nylon hood ornament retaining nut.

NOTE: Be careful not to drop the transit screws into the hood panel cross member.

Replacement hood ornaments are also shipped with transit screws to prevent damage during ship-

Remove the transit screws after the ornament is fitted.