



Sedan Range

DATE 12/96

15-41

SERVICE

TECHNICAL BULLETIN

Radio & CD Autochanger Compatibility – Jaguar Units Mandatory

MODEL 1996-97 MY
Sedan Range

VIN 754304-ON

ISSUE:

Current Jaguar radios will only interface with Jaguar CD Autochangers, not Alpine aftermarket units. When the radio is switched on, the initialization process establishes communication with the changer and checks the part number of the changer to determine if it is a Jaguar unit. If the CD autochanger is not a Jaguar unit, the CD button will remain inoperative.

All radios in parts stock perform the initialization process.

ACTION:

Ensure that the CD Autochanger is a Jaguar unit to avoid problems of incompatibility with the current style radio.